











saab 93 2l turbo (19000 R)



Location **Gauteng, Vereeniging**
<https://www.freeadsz.co.za/x-2131-z>



Car in very good condition, no dents or damages on body. car is not running, got hot of burst pip, dit fiks is, but did poet timing rong wen traaing to start, so need to do

 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>	 <p>saab 93 2l turbo</p> <p>https://www.freeadsz.co.za/x-2131-z</p>
---	--	--	--	---	--	--	--	--	--